



# Surlyn®

resin

## **Surlyn® Troubleshooting Guide and Mold Preparation Checklist**

### **Surlyn® -- Troubleshooting Guide**

<b>Problems</b>	<b>Possible Causes</b>	<b>Possible Solutions</b>
<b>Sprues breaking off-sprues sticking, disrupting cycle</b>	Short "hold" cycle Cold nozzle  Poor cooling around sprue bushing  Long Sprue with improper draft	Increase "hold" time Check heat source and controller for malfunction  Increase cooling to plate containing sprue bushing  Rework bushing to recommended size
<b>Fastener failures on bending immediately after molding</b>	Low melt temperature Excessive fill rate Thin wall thickness Weak weld lines on fastener	Increase "actual" melt temperature Decrease ram speed Rework tool to increase wall See weld line solutions
<b>Fastener failures on installation</b>	Sharp angles on internal ribs that create notch failure Weld line weakness in fastener wall Undersized hold Oversized fastener	Add radii to all internal comers  See weld line solutions Check receptacle specification Check retainer specification
<b>Flash on runners</b>	Cavities too far above cavity plate "Rolled over" runner edges High injection pressure Low clamp pressure	Rework tool to lower inserts Rework cavity plates See parting line flash solutions See parting line flash solutions
<b>Weld lines</b>	Low melt temperature Poor venting Slow fill rate or flow restriction	Check heat source Clean existing vents Add vents to increase fill rate Check rate speed, increase gate size
<b>Non-uniform wall dimension on fastener</b>	Bent core pin Core pin misaligned with cavity Thin wall thickness	Replace, change to harder metal Retool Rework mold to increase wall thickness
<b>Parts too shiny</b>	Improper matte finish Low melt temperature  Low mold temperature	Sandblast Check heat source Use recommended melt temperature Check mold heater Use recommended mold

		temperature
--	--	-------------

<b>Problems</b>	<b>Possible Causes</b>	<b>Possible Solutions</b>
<b>Parts vary in size, shot to shot</b>	Faulty check ring Interrupted cycles due to part sticking sprue sticking, nozzle freeze off	Measure ring for wear Spray mold and sprue with release agent, increase nozzle temperature
<b>Excessive flash on fasteners</b>	High injection pressure  Poor tooling, worn mold Mold hot spot	Lower injection pressure Refer to recommended pressure  Rework tool Check coring for circulation Replace inserts with high heat dissipating metal
<b>Part weight varies shot to shot</b>	Faulty check ring Faulty temperature controller Erratic screw feed (bridging) Poor tooling Wet or excessive regrind	Replace ring Repair or replace controller Check for cooling water on hopper Match fit to eliminate flashing Use regrind same shift Keep regrind ratio below 50%
<b>Variation in part shrink-post molding (poor fit to standard fixture)</b>	Melt temperature change Mold temperature change Unbalanced resin flow to multi-cavities	Check temperature controls Check mold cooler Standardize resin flow to cavities
<b>Variation in dimension change</b>	High injection pressure Low injection pressure Faulty check ring High melt temperature  Low melt temperature	Check hydraulic controls Replace if worn Check heat source controllers Look for excessive back pressure Check heater bands and "actual" melt temperature
<b>Shiny area on part surface</b>	Condensation Contamination from mold release Cold spots in mold Poor venting	Raise mold temperature Clean mold cavity Check for uniform mold coring Open vent in trouble area
<b>Splay on surface</b>	Moisture in resin Contamination	Dry resin Purge until splay disappears Clean barrel if necessary

<b>Problems</b>	<b>Possible Causes</b>	<b>Possible Solutions</b>
<b>Sink marks</b>	Thick cross-section, low injection pressure  Poor gate design Poor venting  Inadequate ram forward time  Not enough material	Retool-using ribs Check hydraulic controls Add foaming agent Recheck molding parameters Increase gate size Add vents to cavity ends or in vicinity of sink Clean existing vents Fill more slowly Add time-refer to checklist Adjust feed setting, check capacity of barrel
<b>Excessive flash on parting line</b>	Poorly tooled cavities Low clamp pressure  Worn cavities High injection pressure Hot mold	Rework mold Check hydraulic setting Set relief valve higher Rework mold Check relief valve operation Check mold heater setting

<b>Part deformation on ejection</b>	Short "hold" cycle Cavities over-filled  High mold temperature	Increase "hold" cycle Decrease pressure Use mold release spray Check relief mold heater Increase cooling water Check coring circulation Slow ejector pins
<b>Warping near gate area</b>	Excessive gate area Excessive injection pressure High fill rate High melt temperature  High mold temperature	Rework tool to recommended size Check pressure setting Decrease ram speed Check heat source and controllers Lower controller setting Check mold heater Increase cooling water Check coring circulation
<b>Corrosion of equipment or tooling</b>	Mild steel surface  Wet resin	Stainless steel or other corrosion-resistant alloys are recommended Pre-dry resin if moisture content is above 0.1%

## ***Surlyn*<sup>®</sup> Mold Preparation Checklist**

### **Introduction**

The first and generally most critical step in molding parts of *Surlyn*<sup>®</sup> resins is proper tool design. This checklist is designed to provide a quick reference source in reviewing the plans of new or modified tool design. For more detailed information, see the PART AND MOLD DESIGN MANUAL for *Surlyn*<sup>®</sup> resin, available from your DuPont Industrial Polymers marketing representative or district office.

### **Sprue Bushing**

- Should be as short as possible.
- Should have 0.75 in. taper/foot (6.2cm, taper/m.) (3° included angle) with sprue opening equal to main runner diameter.
- Should contain a generous radius into main runner.
- Should have all internal surfaces sandblasted for easier release.

### **Runners**

- Should be full round, 0.200 in. (0.5cm.) diameter initially; add 0.062 in. (0.16cm.) for each right angle turn. Do not exceed 0.375 in. (1cm.)
- Should have all dead ends vented.
- Should have a radius at all intersections.
- Should be laid out so each cavity receives equal pressure to insure identical fill pattern.

### **Gates**

- Should have a fan or edge for minimum warpage and shorter molding cycle. Both entrance and exit should flare into cavity Always cut with a minimum land of 0.050 in. (0.13 cm.) and set opening initially at 0.050 in. thick x 0.750 in. (1.9 cm.) wide. Increase as needed to fill cavity
- Should be located on cavity-end, when possible.
- If side-gated, should be cut into cavity wall at an angle to avoid jetting across cavity
- Should begin with a single gate, with option to cut in additional gates every 12 in. (30cm.).

## Cavities

- Should be liquid or air-blasted with an abrasive (i.e. aluminum oxide) for matte finished parts. Grit size and total treatment time dependent on metal hardness.
- Should have maximum wall thickness no greater than 0.250 in. (0.6 cm.). Radius all intersections with a minimum of 0.015 in. (0.04 cm.).
- Should contain rib thickness of one-half to two-thirds of main wall thickness. Radius all intersections a minimum of 0.015 in. (0.04 cm.).
- Should have fastener walls with a minimum thickness of 0.060 in. (0.15 cm.) and supporting ribs from the cavity bottom. Radius all intersections.

## Vents

- Vents are needed at all dead ends, opposite all gates, and in the vicinity of all weld lines. Preferably peripheral venting of cavity runner is suggested.
- Runners-size vents to 0.0015-0.002 in. (0.04-0.05 mm.) deep over runner width. Use land length of 0.032 in. (0.8 mm.) and increase vent depth beyond land ending to 0.032 in. (0.8 mm.). Carry channel to atmosphere.
- Cavities-size vents to 0.0015-0.002 in. (0.04--0.05 mm.) deep and 0.250 in. (0.6 cm.) wide. Same details for land. Carryout channel as runners.
- Pins-grind vents to 0.0015-0.002 in. (0.04-0.05 mm.) flat or slot on pin for 0.250 in. (0.6 cm.). Open to 0.032 in. (0.8 mm.) beyond and carry to atmosphere.

## Mold Cooling

- Core the cavity side with a series of small channels, 0.437 in. (1.1 cm.) in diameter. Locate no further than one diameter distance from the cavity surface.
- Locate adequate cooling cores in the vicinity of all runners and the sprue bushing.
- Use high thermal conductivity metals (beryllium, copper, etc.) where coring is not possible, particularly in core pins that are not water cooled.

## Materials of Construction

- Stainless steel or other corrosion-resistant alloys are recommended. Older machines may be attacked if they have mild steel parts.
- Use of excessively wet resin accelerates the corrosion rate of mild steel.

## *Surlyn*<sup>®</sup> Checklist for Processing Conditions

### Be sure to check the following:

- Water cooling on hopper throat is functioning
- Maximum rear zone temperature is 350°F (175°C)
- Melt temperature is 460°F (238°C)\* (as verified by pyrometer)
- Injection Pressure is 10-12,000 psi nominal\* (700-850kg/sq. cm.)
- Fill rate is 5 to 8 sec \*
- Pad (positive cavity pressure) is 0.325 in. (8 mm)
- Injection forward time is 40 sec. ± 5 (For 0.125 in. (3 mm) part thickness)
- Hold cycle time is 20 sec. ± 10 (For 0.125 in. (3 mm) part thickness)
- Back pressure is 50-200 psi (3-14 kg/sq. cm.)
- Mold temperature is 60°F ± 10° (15°C ± 5°)
- Resin is dry

\* Adjust as needed-only guidelines

## Safety

As with any hot material, care should be taken to protect the hands and other exposed parts of the body when handling molten polymer. At temperatures above 250°C (482°F), *Surlyn*<sup>®</sup> resins can evolve low concentrations of fumes. It is recommended that adequate ventilation be provided. For more detailed information on the safe handling and disposal of DuPont ethylene resins, OSHA material safety data sheets and a Product Safety Bulletin can be obtained from the sales representative serving you.

Protective covering should be worn since molten resin is very tacky and will stick to the skin.

---



©1999 DuPont Company.  
All rights reserved.



We welcome and respond promptly to [e-mail](#).

The technical data contained herein are guides to the use of DuPont resins. The advice contained herein is based upon tests and information believed to be reliable, but users should not rely upon it absolutely for specific applications because performance properties will vary with processing conditions. It is given and accepted at user's risk and confirmation of its validity and suitability in particular cases should be obtained independently. The DuPont Company makes no guarantees of results and assumes no obligations or liability in connection with its advice. This publication is not to be taken as a license to operate under, or recommendation to infringe, any patents.

CAUTION: Do not use in medical applications involving permanent implantation in the human body. For other medical applications, see "[DuPont Medical Caution Statement](#)", H-50102.